KEY TO FORMATION LOG

Brown Clay - br cl
Blue Clay - bl cl
Sand - sd
Sandy Clay - sdy cl
Soft Shale - s shl
Hard Rock - hd rk
Sandstone - ss
Fine Gravel - f gr
Boulders - bdrs

Invoice No.....

FIELD REPORT

204140365

# MIDNIGHT SUN

DRILLING CO. LTD.

105D14

#204140365

Mailing Address:
P.O. Box 2106
Whitehorse, Yukon
Phone: 667-4795

Job (Month) (Day) (Year)
Started. MAY..11..1971..
Completed. MAY.14..1971..

[redacted]

| NAME AND ADDRESS OF CLIENT | DESCRIPTION OF WORK | LOCATION OF WORK |
|---|---|---|
| [redacted] Mile 4.5 | WATER WELL | ~~Sec.~~ ~~Twp.~~ ~~Rge.~~ ~~W.~~ Mile 4.5 Mayo Rd |

| FORMATION LOG FROM | TO | FORMATION | DESCRIPTION OF WORK | TIME Date | From | To | Hours |
|---|---|---|---|---|---|---|---|
| | | | Move FROM CURRIE'S | | | | |
| | | | TAGISH SET UP MAY 10 | | | | |
| 0 | 49 | SAND | } DONE BY OTHERS | | | | |
| 49 | 88 | SILT WATER BEARING | | | | | |
| ~~88~~ | 131 ~~133~~ | BLUE CLAY | | 11 ~~11~~ | 09:00 ~~09:00~~ 13:00 | 12:00 18:00 | 8 |
| 131 | 132 | GRAVEL | | | | | |
| 132 | 136 | BLUE CLAY | | 12 | 09:00 15:00 | 14:00 | |
| 136 | 137 | GRAVEL | | | | | |
| 137 | 161 | SANDY CLAY | | | | | |
| 161 | 174 | GRAVEL | PERFORATED | | | | |
| 174 | | SEEMED LIKE BED ROCK | | | | | |
| | | | STATIC LEVEL 94' | | | | |
| | | | VERY SLOW RECOVERY | | | | |

Rcrd. of Casing & Pipe

| Size | Type | Size | Type |
|---|---|---|---|
| Feet | Inch | Feet | Inch |

Remarks: Poor quality water from grl
No yield from bedrock

| | | |
|---|---|---|
| Well Cased: Casing to ft. and | Total Big Time (above) | hrs. |
| Casing from ft. to ft. | Total Standby (above) | hrs. |
| STATIC LEVEL: from ground level from top of casing | Drilling Mud Used (above) 10 | sacks |

SIGNATURES

For Midnight Sun.....

For Client.....