20414 0371

Field Report

105 D 14

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.
PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

[redacted]

Started Nov. 20 19 9[redacted]

Completed Nov. 20 19 9[redacted]

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Acorn Sawmill	Cleanout Water Well.	Mile 7 Mayo Road
	rig 1	

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			Move on Set up.				
			& Trip in to Bottom.				
			Pump Water Down hole.				
			to Clean out				
					total time		
			Travel Back to Shop.		5 hours.		
			5 HRS. @ 220/HR.				

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks:

Static Level was at 15' & Rising

5" casing

Static Level	15' +	Total Rig Time	5 hrs.
Ground Level		Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN [redacted] .....

TITLE.....

CLIENT.....

TITLE.....

Willow Printers