



# Field Report

211030017

Started Apr. 26.....1990

Completed Apr. 29...1990

PH. 633-3070 TELEX 036-8496  
P.O. BOX 4391  
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
[REDACTED]	W/W	Tintina sub Div. Far Lot #10
	90-1A-8	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move on set up	Apr. 26	7:30	9:30	2
0	3	silt	Gr.	"	9:30	11:00	1.5
3'	20'	till					
20	70	till	Broke casing last 24' plus shoe moved 5'	Apr 27	7:00	9:30	14.5
0	3'	silt Gr.					
3	80'	till	Broke shoe from casing pulled casing replaced oring in Hyd. Bank				
0'	3'	silt Gr.		Apr. 28	7:00	6:00	11
3'	173	till					
173	225	BR					
			move off Drill stuck Flat Deck still stuck	"	6:00	10:00	4
			Pull 51 out loading	APR 29	8:30	11:00	2.5
			Travel to Wheel.	"	11:00	4:30	1.5

Rcrod. of Casing & Pipe

Size	Type	Size	Type
Feet	Inch	Feet	Inch
6 5/8			
178			

Remarks:

Last 24' casing Plus shoe.  
3-odox shoe.

Nowater

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN...

(Driller)

CLIENT

TITLE.....

(Helper)

TITLE.....