MIDNIGHT SUN DRILLING CO. LTD.
PH. 667-6144
WHITEHORSE Y.T.
P.O. Box 4391

FIELD REPORT

Typhoon Sun

213120017

Started June 29 1980

Completed.....19....

Group Home

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Haldane contracting Box 13 Mayo.	W/W	Mayo.

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			moving on setting up	June 29	1:30	2:30	1
0'	17'	silt		"	2:30	11:00	8.5
17'	20'	fine sand					
20'	26'	silt	Frozen				
26'	123'	clay silt	Frozen				
123'	120'	silt	Clay.				
			traveling to whitehorse	June 30	8:00	1:00	5
			Loading at shop	"	1:00	2:00	1
			loading	July 2	8:00	11:00	3
			traveling	"	12:00	5:30	5.5
120'	268'	silt	Clay.	"	5:30	1:00	7.5
268'	300	Brown	Till				
			moving to Mayo	"	1:00	1:30	.5
			traveling	"	1:30	5:00	3.5
			Traveling	"	8:00	11:00	3

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch
299'			

Remarks:

STATIC LEVEL	Total Rig Time 38.5 hrs.
Ground level	Total Standby hrs.
Top of casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....