


B-ID #1 802030010

Field Report #2 802030011



PH. 633-3070 TELEX 036-8496
 P.O. BOX 4391
 WHITEHORSE, YUKON

Started Sept. 20.....1985

Completed Sept. 22.....1985

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
SERVICE AND SUPPLY	W/W	Yukon River
	89-1A-31	Campground Dawson

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE ^{LOAD AND} TRAVEL TO Pelly	Sept 19	8:00	2:00	6
			Travel to Dawson	Sept 20	11:30	4:30	5
			Hole #1 move on setup	"	5:00	6:00	1
0	3	Peat		11	6:00	8:00	2
3	15	silt					
15	32	Gr. silt					
32	40	BR					
40	200	BR		Sept 21	7:30	5:00	9.5
			Hole #2 move setup	"	5:00	6:30	1.5
0	3	Peat		11	6:30	8:30	2
3	17	silt					
17	39	Gr. silt					
39	40	BR					
40	160	BR		Sept 22	7:30	12:00	4.5
			Develop	"	12:00	2:30	2.5
			move off	"	2:30	3:00	0.5

Rcrd. of Casing & Pipe				Remarks:		
Size	Type	Size	Type			
				Hole #1		
				45' casing		
Feet	Inch	Feet	Inch	1-6" odex shoe (ss)		
				Hole #2		
				1-6" odex shoe (ss)		
				44' 6" casing		
				1 GPM		
				static - 47' + rising		
				Static Level	Total Rig Time	hrs.
				Ground Level	Total Standby	hrs.
				Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....