MIDNIGHT SUN DRILLING CO. LTD.
PH: 668-2434
WHITEHORSE Y.T.
P.O. Box 4391

FIELD REPORT

#802030024

Started June 13 ..... 19 77
Completed ... June 13 .... 1977 ..

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Stanley and Associates 212 Main St. Whitehorse, Y.T.	#2 Test Well	Junction of 3/11 hwys.

FORMATION LOG FROM	TO	FORMATION
0'	1'	fill
1'	2'	peat
2'	16'	gravel
16'	20'	silty sand
20'	83'	silty sand till
83'	86'	silty sand till rocks
86'	107'	silty sand till

DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
MOVE				
moved from #1 to #2 hole and setting-up drilled to 107'	June 13	8am	10pm	12
moved to #3 hole				

Rcrd. of Casing & Pipe Size	Type	Size	Type
6"			
Feet	Inch	Feet	Inch
20'			

Remarks: Reamed to 7 7/8" to 16'.
Set 6" to 20' and pulled
drilled from 20' to 107'

STATIC LEVEL	
Ground level moving	
Top of casing	

Total Rig Time	10	hrs.
~~Total Standby~~	3	hrs.
Drilling Mud	4	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT [redacted].....
TITLE.....