MIDNIGHT SUN DRILLING CO. LTD.
PH: 668-2434
WHITEHORSE Y.T.
P.O. Box 4391

FIELD REPORT

802030025

Started June 12 1977
Completed June 12 1977

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Stanley and Associates 212 Main Street Whitehorse, Y.T.	Test Hole #1 for water well	Industrial Site #2 19 miles from Dawson

FORMATION LOG FROM	TO	FORMATION
0'	4'	peat
4'	5'6"	silt
5'6"	21'	gravel(frozen)
21'	25'	silt
25'	35'	silt, till
35'	47'	silt
47'	72'6"	hard till
72'6"	80'	silty till
80'	100'	silt

DESCRIPTION OF WORK	DATE	TIME FROM	TO	HOURS
MOVE Drilling on old road moved off and drilled to ~~100'~~	June 12	8am	9:30am	1.5
		9:30am	11:30am	2
		11:30am	8pm	8.5

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks: Drilled from 25'--100' 6¼" wing bit

STATIC LEVEL		Total Rig Time	10.5 hrs.
Ground level	Moving	~~Total Standby~~	1.5 hrs.
Top of casing		Drilling Mud	4 sacks

SIGNATURES

MIDNIGHT SUN [redacted].....
TITLE.....

CLIENT [redacted].....
TITLE.....