

**Government of Yukon,
Yukon Housing
Corporation**

Testpit No: AST Area

Project: Limited Phase II Environmental Site Assessment

Project No: [REDACTED]

Location: 807 Lakeview Avenue

Watson Lake, Yukon

UTM: 516255 E; 6658595 N; Z 9

Depth (m)	Method	Soil Description	Ground Ice Description	Sample Type	Moisture Content (%)	Depth (ft)
0					Plastic Limit: 20 Moisture Content: 40 Liquid Limit: 80	0
0 - 1.2	Excavated	GRAVEL - sandy, trace silt, covered by 0.5 m sandy frozen berm, medium to coarse gravel, medium to coarse sand - cobbly, no to trace sand, medium brown, coarse sand, cobbles to 250 mm diameter	Frozen			0 - 4
1.2		END OF TESTPIT (1.2 metres)				4 - 9

Archive

[REDACTED]	Contractor: [REDACTED]	Completion Depth: 1.2 m
[REDACTED]	Drilling Rig Type: Excavator	Start Date: 2021 March 1
[REDACTED]	Logged By: JH	Completion Date: 2021 March 1
[REDACTED]	Reviewed By:	Page 1 of 1