

**Government of Yukon,
Yukon Housing
Corporation**

Testpit No: Tank nest area/21TP01

Project: Limited Phase II Environmental Site Assessment

Project No: [REDACTED]

Location: 807 Lakeview Avenue

Watson Lake, Yukon

UTM: 516274 E; 6658595 N; Z 9

Depth (m)	Method	Soil Description	Ground Ice Description	Moisture Content (%)	Plastic Limit	Moisture Content	Liquid Limit	Depth (ft)
0		CRUSHED ROCK - (100 mm thick)	Frozen					0
		GRAVEL - silty, sandy, cobbly, medium brown, (300 mm thick)						1
		CLAY - stratified, reddish brown, oxidized, black lens, (200 mm thick)						2
		GRAVEL - sandy, pebbles, gravel, cobbles, no to trace silt, medium to coarse sand						3
1	Excavated	- moist	Unfrozen					4
2		END OF TESTPIT (2.0 metres)						5
								6
								7
								8
								9
3								

Archive

[REDACTED]

Contractor: [REDACTED]
 Drilling Rig Type: Excavator
 Logged By: [REDACTED]
 Reviewed By:

Completion Depth: 2 m
 Start Date: 2021 March 2
 Completion Date: 2021 March 2
 Page 1 of 1