



Borehole No: BH21-15

Project: Watson Lake Infrastructure Upgrades

Project No: [REDACTED]

Location: Canyon Boulevard

Watson Lake, Yukon

UTM: 515583 E; 6658052 N; Z 9

Depth (m)	Method	Soil Description	Ground Ice Description	Sample Type	Sample Number	Moisture Content (%)	Plastic Limit	Moisture Content	Liquid Limit	Depth (ft)
0							20	40	80	0
0 - 2.44	Solid stem auger	<p>SAND (FILL) - road crush, gravelly, trace silt, angular to subangular gravel, damp, grey, (150 mm thick)</p> <p>SAND - silty, gravelly, subrounded to rounded gravel, fine to medium grained sand, damp, light brown</p> <p>- large cobble</p> <p>- rock</p>	Unfrozen		SA57	8.3				0 - 8
2.44		<p>END OF BOREHOLE (2.44 metres)</p> <p>Note: Stopped due to refusal on rocks</p>								8 - 32

[REDACTED]

Contractor: [REDACTED]
 Equipment Type: Truck mounted
 Logged By: [REDACTED]
 Reviewed By: [REDACTED]

Completion Depth: 2.44 m
 Start Date: 2021 October 21
 Completion Date: 2021 October 21
 Page 1 of 1