



# Borehole No: BH21-17

Project: Watson Lake Infrastructure Upgrades

Project No: [REDACTED]

Location: 7 Street South

Watson Lake, Yukon

UTM: 516475 E; 6658190 N; Z 9

Depth (m)	Method	Soil Description	Ground Ice Description	Sample Type	Sample Number	Moisture Content (%)	Plastic Limit	Moisture Content	Liquid Limit	Depth (ft)
0		BITUMINOUS SURFACE TREATMENT SAND - gravelly, silty, subrounded to subangular gravel, fine to coarse grained sand, damp, light brown	Unfrozen							0
1	Solid stem auger	- greyish brown			SA61	6.7				3
2		- (Gravel - 29%; Sand - 44%; Silt & Clay - 27%)			SA62	5.3				7
3		- large cobble or boulder								10
4					SA63	6.9				13
5					SA64	5.9				17
6		END OF BOREHOLE (6.10 metres) Note: Target depth reached								20
7										23
8										26
9										29
10										32

[REDACTED]

Contractor: [REDACTED]

Completion Depth: 6.1 m

Equipment Type: Truck mounted

Start Date: 2021 October 21

Logged By: [REDACTED]

Completion Date: 2021 October 21

Reviewed By: [REDACTED]

Page 1 of 1