



Borehole No: BH21-21

Project: Watson Lake Infrastructure Upgrades

Project No: [REDACTED]

Location: Wye Drive

Watson Lake, Yukon

UTM: 518182 E; 6657840 N; Z 9

Depth (m)	Method	Soil Description	Ground Ice Description	Sample Type	Sample Number	Moisture Content (%)	Plastic Limit	Moisture Content	Liquid Limit	Depth (ft)
0							20	40	80	0
0	Solid stem auger	SAND AND GRAVEL - trace silt, fine to coarse grained sand, subangular to subrounded gravel, damp, greyish brown	Unfrozen							
1		- larger subrounded to rounded gravel and cobbles			SA77	2.4				3
2		- (Gravel - 46%; Sand - 48%; Silt & Clay - 6%)				SA78	2.7			7
4		- wet				SA79	11.1			13
5						SA80	3.5			17
6		END OF BOREHOLE (6.10 metres) Note: Target depth reached								20
7										23
8										26
9										29
10										32

Contractor: [REDACTED]

Completion Depth: 6.1 m

Equipment Type: Truck mounted

Start Date: 2021 October 21

Logged By: [REDACTED]

Completion Date: 2021 October 21

Reviewed By: [REDACTED]

Page 1 of 1