



Borehole No: BH21-27

Project: Watson Lake Infrastructure Upgrades

Project No: [REDACTED]

Location: Spruce Street

Watson Lake, Yukon

UTM: 518376 E; 6658396 N; Z 9

Depth (m)	Method	Soil Description	Ground Ice Description	Sample Type	Sample Number	Moisture Content (%)	Plastic Limit	Moisture Content	Liquid Limit	Depth (ft)
0							20	40	80	0
0 - 1	Solid stem auger	SAND AND GRAVEL - trace silt, fine to coarse grained sand, subangular to subrounded gravel, damp, light brownish grey	Seasonally frozen Unfrozen							1
1 - 3		- (Gravel - 61%; Sand - 35%; Silt & Clay - 4%)		SA106	2.6					3
3 - 10		END OF BOREHOLE (3.05 metres) Note: Target depth reached								10
10 - 32										11 - 32

[REDACTED]

Contractor: [REDACTED]

Completion Depth: 3.05 m

Equipment Type: Truck mounted

Start Date: 2021 October 24

Logged By: [REDACTED]

Completion Date: 2021 October 24

Reviewed By: [REDACTED]

Page 1 of 1