



Borehole No: BH21-29

Project: Watson Lake Infrastructure Upgrades

Project No: [REDACTED]

Location: Woodland Crescent

Watson Lake, Yukon

UTM: 518788 E; 6658272 N; Z 9

Depth (m)	Method	Soil Description	Ground Ice Description	Sample Type	Sample Number	Moisture Content (%)	Plastic Limit	Moisture Content	Liquid Limit	Depth (ft)
0							20	40	80	0
0 - 3.05	Solid stem auger	SAND - gravelly, trace silt, trace cobbles, fine to coarse grained sand, subangular to subrounded gravel, damp, light brownish grey	Unfrozen							
5.8					SA110	5.8				6.1
2.7					SA111	2.7				2.8
3.05		END OF BOREHOLE (3.05 metres) Note: Target depth reached								10
10										32

[REDACTED]

Contractor: [REDACTED]

Completion Depth: 3.05 m

Equipment Type: Truck mounted

Start Date: 2021 October 24

Logged By: [REDACTED]

Completion Date: 2021 October 24

Reviewed By: [REDACTED]

Page 1 of 1