



Borehole No: 21BH15

Project: [REDACTED] Project No: [REDACTED]
 Location: Tagish Avenue Ground Elev: 665.271 m
 Carcross, Yukon UTM: 515672.022 E; 6670527.943 N; Z 8

Depth (m)	Method	Soil Description	Sample Type	Notes and Comments	Elevation (m)
0					
0				Pipe stickup = 1.00 metre	
1	Sonic	SAND - trace gravel, roots, fine to medium grained sand, medium brown to orange, frozen to 0.60 metres			
1		- moist			
2		- trace to no visible gravel, dry			
3		- slight organic discolouration			
4					
5		- 50 mm thick black discolouration			
6		- medium to coarse grained sand, damp, medium brown to orange			
7		- fine to medium grained sand			
8	- light grey silty sand lens				
9		- 100 mm thick medium to coarse grained sand lens			
9		No recovery			
10		SAND - silty, trace clay, fine grained sand, low to medium plastic silt, grey, trace to no visible black organics, no visible staining, no discernible hydrocarbon odour			
11		- very wet			
12		- wet			
13		END OF BOREHOLE (13.25 metres)			
14		water - 8.73 metres on December 15, 2021			
15		Monitoring well installed to 11.50 metres			
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					

Contractor: [REDACTED]	Completion Depth: 13.25 m
Equipment Type: Truck mounted	Start Date: 2021 December 9
Logged By: [REDACTED]	Completion Date: 2021 December 9
Reviewed By:	Page 1 of 1