

PROJECT: 952-15231

RECORD OF BOREHOLE: BH95G-32

SHEET 1 OF 1

LOCATION: 6816133N, 415009E, NW WASTE DUMP

DRILLING DATE: Aug. 22/23, 1995

DATUM: NAD 83

INCLINATION: -90 AZIMUTH:

DRILL RIG: Boyles Brothers - Rotary

DRILLING CONTRACTOR: D.J. Drilling



DEPTH SCALE METRES	DRILLING RECORD	SYMBOLIC LOG	ELEV. DEPTH (m)	RUN No.	PENETRATION RATE (mm/min)	FLUSH	COLOUR	% RETURN	FR-FRACTURE		F-FAULT		SM-SMOOTH		FL-FLEXURED		NOTES TEST RESULTS			
									CL-CLEAVAGE	SH-SHEAR	J-JOINT	P-POLISHED	R-ROUGH	ST-STEPPED	UE-UNEVEN	W-WAVY				
									VN-VEIN	S-SLICKENSIDED	PL-PLANAR	C-CURVED								
RECOVERY		R.Q.D. %	FRACT. INDEX PER 0.3m	DISCONTINUITY DATA		ROCK STR. (MPa)	WEATHERING INDEX (w)													
TOTAL CORE %	SOLID CORE %			TYPE AND SURFACE DESCRIPTION	DP w.r.t. CORE AXIS															
0	Ground Surface		1385.85																	
1	Compact to dense, brown SAND, some gravel, trace to some silt, occasional cobbles.		0.00	1																
2																				
3																				
4																				
5																				
6			1380.15	6																
7	Dense to very dense, grey SAND and GRAVEL, trace to some silt, occasional cobbles.		6.70	7																
8																				
9																				
10																				
11	Bedrock - biotite porphyry dyke matrix.		1376.79	10																
12																				
13	Quartz vein inclusions of mafic volcanic Biotite SCHIST.		1374.85	11																
14																				
15	Chlorite SCHIST with disseminated biotite and calcite.		1373.15	12																
16																				
17	End of Borehole		1370.70	13																
18			16.15																	

DATA FORM: ROCKMVS

DATA INPUT: BAD SEPT 95

DEPTH SCALE: 1 to 100

CLIENT: Cominco
Golder Associates

LOGGED: []
DATE: Aug. 22/23, 1995
CHECKED: []

Bentonite Seal

Aug. 26, 1995

Sand Pack

32mm dia. PVC Screen

WC = 3.5%

J,PL & I
S-R

J,PL,S

J/B,PL,S
R

B/PL,R

B/RL-1/R