

PROJECT No.: 11-1436-0073 (2800)

# RECORD OF MONITORING WELL: DC-MW12-01

SHEET 1 OF 1  
DATUM: Local

CLIENT: Yukon Government Community Services  
PROJECT: Yukon Landfill Assessment  
LOCATION: Drury Creek

DRILLING DATE: July 12, 2012  
DRILLING CONTRACTOR: Midnight Sun Drilling

N: -6896737.3 E: -530960.465  
Note: Northing and Easting Coordinates have been determined by GPS in the field and are approximate only.

DEPTH SCALE METRES	BORING METHOD	SOIL PROFILE		SAMPLES				PID ppm		WATER CONTENT PERCENT Wp  -----  WI	ADDITIONAL LAB. TESTING	PIEZOMETER, STANDPIPE OR THERMISTOR INSTALLATION
		DESCRIPTION	STRATA PLOT	ELEV. DEPTH (m)	NUMBER	TYPE	BLOWS/0.3m	CORE No.	CORE RECOVERY %			
0	M5 Drilltech Truck Mounted Auger Drill Rig Air Rotary	Ground Surface (ML) sandy SILT, some clay, brown to grey, wet.		0.00							Stickup = 0.97m	
1		(GW-SW) GRAVEL and SAND, well graded, moist.		0.91								
4		(SM) SILTY fine SAND, brown, moist.		3.96								
5		- wet at 5.18m depth.										
8.23		End of Monitoring Well.										

File:\BURN-CGAP\PCS\PROJECTS\2011\1436\11-1436-0073\DRIFTING\GINTV11-1436-0073 (2800 DC).GPJ Output Form:BC\_BOREHOLE (ENVIRO) Template:BC REGION TEMPLATE BETA 1.GDT Library:BC REGION LIBRARY.GLB Date:2012/08/13/12

DEPTH SCALE  
1 : 50



LOGGED: CB  
CHECKED: **DRAFT**