

PROJECT No.: 11-1436-0073 (1100)

# RECORD OF MONITORING WELL: FA-MW12-02

SHEET 1 OF 2  
DATUM:

CLIENT: Yukon Government Community Services  
PROJECT: Yukon Landfill Assessment  
LOCATION: Town of Faro

DRILLING DATE: July 11, 2012  
DRILLING CONTRACTOR: Midnight Sun Drilling

DEPTH SCALE METRES	BORING METHOD	SOIL PROFILE		SAMPLES				PID ppm		WATER CONTENT PERCENT Wp  -----  Wl	ADDITIONAL LAB. TESTING	PIEZOMETER, STANDPIPE OR THERMISTOR INSTALLATION											
		DESCRIPTION	STRATA PLOT	ELEV. DEPTH (m)	NUMBER	TYPE	BLOWS/0.3m	CORE No.	CORE RECOVERY %				5	10	15	20							
0	M5 Ditcher Truck Mounted Auger Drill Rig Air Rotary	Ground Surface (SW-GW) SAND and GRAVEL, dark grey-brown, moist.		0.00																			
7.32		(ML) CLAYEY SILT, some sand, trace gravel, dark grey, wet.																					
9.75		(SM) SILTY SAND, trace gravel, dark grey-brown, moist.																					
CONTINUED NEXT PAGE																							

Bentonite Seal

DEPTH SCALE  
1 : 50



LOGGED: AB  
CHECKED: **DRAFT**

File:\BUR-GRAPICS\PROJECTS\2011\1436-0073\DRRAFTING\GINTY\1-1436-0073 (1100) FA\GPF Output Form\BIC\_BOREHOLE (ENVIRO) Template\BIC REGION TEMPLATE BETA 1.GDT Library\BIC REGION LIBRARY.GLB Idoc\idocak 08/13/12

