


| | | |
|----------------------------------|--------------------------------|----------------------------|
| ABS MONITORING WELL INSTALLATION | ARCTIC BACKHOE SERVICES | PROJECT NO. - BOREHOLE NO. |
| LEASE 105D11/6/810LTF | DRILL: AIR ROTARY | ENVSWM03344-02-14MW03 |
| WHITEHORSE, YUKON | 6726289.05N; 494527.3E; Zone 8 | ELEVATION: 822.15 m |


| | | | | | | |
|---------------|------------------------------------|--------------------------------------|---------------------------------|-----------------------------------|---|-------------------------------|
| SAMPLE TYPE | <input type="checkbox"/> DISTURBED | <input type="checkbox"/> NO RECOVERY | <input type="checkbox"/> SPT | <input type="checkbox"/> A-CASING | <input type="checkbox"/> SHELBY TUBE | <input type="checkbox"/> CORE |
| BACKFILL TYPE | <input type="checkbox"/> BENTONITE | <input type="checkbox"/> PEA GRAVEL | <input type="checkbox"/> SLOUGH | <input type="checkbox"/> GROUT | <input type="checkbox"/> DRILL CUTTINGS | <input type="checkbox"/> SAND |



| | |
|-----------------|--------------------------|
| LOGGED BY: KR | COMPLETION DEPTH: 43.58m |
| REVIEWED BY: RM | COMPLETE: 14/09/23 |
| DRAWING NO: | Page 1 of 2 |

| | | |
|----------------------------------|--------------------------------|----------------------------|
| ABS MONITORING WELL INSTALLATION | ARCTIC BACKHOE SERVICES | PROJECT NO. - BOREHOLE NO. |
| LEASE 105D11/6/810LTF | DRILL: AIR ROTARY | ENVSWM03344-02-14MW03 |
| WHITEHORSE, YUKON | 6726289.05N; 494527.3E; Zone 8 | ELEVATION: 822.15 m |

| | | | | | | |
|---------------|------------------------------------|--------------------------------------|---------------------------------|-----------------------------------|---|-------------------------------|
| SAMPLE TYPE | <input type="checkbox"/> DISTURBED | <input type="checkbox"/> NO RECOVERY | <input type="checkbox"/> SPT | <input type="checkbox"/> A-CASING | <input type="checkbox"/> SHELBY TUBE | <input type="checkbox"/> CORE |
| BACKFILL TYPE | <input type="checkbox"/> BENTONITE | <input type="checkbox"/> PEA GRAVEL | <input type="checkbox"/> SLOUGH | <input type="checkbox"/> GROUT | <input type="checkbox"/> DRILL CUTTINGS | <input type="checkbox"/> SAND |



| | |
|-----------------|--------------------------|
| LOGGED BY: KR | COMPLETION DEPTH: 43.58m |
| REVIEWED BY: RM | COMPLETE: 14/09/23 |
| DRAWING NO: | Page 2 of 2 |