







Project		Groundwater Monitoring Well Installations		Project #		W801500	
Location		Al's Environmental Cleanup Inc. LTF		BH number		MW07	
LSD				Zone		08V	
Community		Mayo, YT		GPS		0457328 E 7057887 N	
Sample type		<input type="checkbox"/> Disturbed <input checked="" type="checkbox"/> No Recovery		Elevation (mas)		557	
Backfill type		<input checked="" type="checkbox"/> Bentonite <input type="checkbox"/> Slough <input type="checkbox"/> Concrete <input type="checkbox"/> Filter sand <input type="checkbox"/> Drill cuttings					
Depth (m)		Soil Discription		MW07		Sample Type	
from	to					Depth (m bgs)	
0.85	0.00	PVC stick up					
0.00	0.30	Organics					
0.30	11.58	SAND, gravel, silt, dry light brown 0.304 m top of bentonite 0.609 m top of drill cuttings					
11.58	18.00	SAND, gravel, trace silt, dry light brown 12.95 m top of bentonite 13.56 m top of sand 14.18 m top of screen 14.63-15.24 m more silt, damp to wet					
						▼ 16.40	
18.00	18.75	GRAVEL, cobbles very slow drilling					
		End of hole at 18.75 m					
West 80 Environmental Consulting Ltd.							