MIDNIGHT SUN DRILLING CO. LTD.
PH. 667-6144
WHITEHORSE Y.T.
P.O. Box 4391

FIELD REPORT

Started..July..26.....19.79.

Completed.July..28.....1979..

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Parks and Historic Resources	water well	Lapie River

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
0'	2'	silt		July 26	8:00	9:00	12
2'	7'	gravel	Developed hole cave casing				
7'	8'	rock	shoe bent pulled 34'1" casing	July 27	8:00	2:30	6.5
8'	9'	till	drilled and cased to 52'		2:30	10:00	7.5
9'	24'	frost-silt-some gravel					
24'	31'	frost-gravel-silt					
31'	43'	rock-some gravel-silt layers					
43'	124'	rock	reamed to 122'	July 28	8:00	8:00	12
			broke cone off bit				
			developing				
			moving off,travelling				

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch
52'	5"		

Remarks: water at 115'

developed at 25 G.P.M.

2-5 7/8" bits

2-shoes

STATIC LEVEL	Total Rig Time 38 hrs.
Ground level	Total Standby hrs.
Top of casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....