

SUBSURFACE PROFILE		Description	Sample I.D.	PID (ppm)	Comments	
Depth (m)	Symbol					
0		SILT, some Sand (fine) BROWN, Dry [0.0m - 1.5m]	6-1 #1	1	REFUSAL ENCOUNTERED AT 1.5M WITH THE GEOPROBE DRILL RIG. POSSIBLY DUE TO STEEL OR WOOD - ORGANICS OBSERVED IN DRILL BIT. HOLE ADVANCED BEYOND REFUSAL DEPTH WITH A SOLID STEM AUGER DRILL RIG.	
			6-1 #2	2		
			6-1 #3	2		
			6-1 #4	1		
			6-1 #5	1		
1		Cobbly, Sandy (fine), some Silt, Gravel BROWN, Dry [1.5m - 2.9m]	6-1 #6	1		METAL WIRE DEBRIS THROUGHOUT LAYER FROM 1.5 M - 2.5 M DEPTH
			6-1 #7 LIMITED SAMPLE VOLUME	1		
			6-1 #8	2		
			6-1 #9	2		
			6-1 #10	3		
		END OF HOLE @ 2.9m				