

SUBSURFACE PROFILE					
Depth (m)	Symbol	Description	Sample I.D.	PID (ppm)	Comments
0		SILT, some Sand (fine) BROWN, Dry [0.0m - 1.5m]	6-2 #1 SOME ORGANICS FOUND AT 1.5 M	3	REFUSAL ENCOUNTERED AT 1.5 M, ORGANICS OBSERVED IN DRILL BIT
			6-2 #2	2	
			6-2 #3	0	
			6-2 #4	1	
1			6-2 #5	1	
			6-2 #6	2	
			END OF HOLE @ 1.5m		