

SUBSURFACE PROFILE			Sample I.D.	PID (ppm)	Well Details	Well Drawing
Depth (m)	Symbol	Description				
0	[Hatched Pattern]	CLAY, some Silt, trace Sand (fine) grey brown, Moist [0.0m - 2.0m]	5-3 #1	0		[Hatched Pattern]
1						
2						
2	[Hatched Pattern]	CLAY, trace Silt, Sand (fine) Reddish Grey, Moist [2.0m - 5.0m]	5-3 #2 strong HC smell	165	bentonite	[Hatched Pattern]
3			5-3 #3	124		
4			5-3 #4	29		
5			5-3 #5, Dup A	2		
5	[Hatched Pattern]	CLAY, some Silt Grey, Wet [5.0m - 5.9m]	5-3 #6	1		[Hatched Pattern]
6						
6	[Dotted Pattern]	some Sand (medium), Sand (coarse), Gravel, trace Sand (fine)	5-3 #7	0	silica sand	[Dotted Pattern]
6.5						
7						
6.5	[Dotted Pattern]	CLAY, trace Silt Grey Brown, Wet [6.4m - 6.9m]	5-3 #8	0	Slotted PVC (Schedule 0.012)	[Dotted Pattern]
7						
8						



Contractor: Midnight Sun Drilling
 Operator(s): [REDACTED]
 Method: Hollow Stem Auger

Date: 17/05/2016
 Time: 3:00 PM
 Temperature: 15 °C
 Logged by: [REDACTED]