

PROJECT No.: [REDACTED]

# RECORD OF BOREHOLE: MW15-37/SV15-08

SHEET 1 OF 1

CLIENT: Environment Yukon (SARU)  
PROJECT: Center of Hope  
LOCATION: Whitehorse, YT

DRILLING DATE: December 4th, 2015  
DRILLING CONTRACTOR: Midnight Sun Drilling

DATUM: NAD 83

DEPTH SCALE METRES	DRILLING RIG DRILLING METHOD	SOIL PROFILE		GEOTECH SAMPLES				CHEMISTRY SAMPLES		PID ppm	DYNAMIC PENETRATION RESISTANCE, BLOWS/0.3m				ADDITIONAL LAB. TESTING	PIEZOMETER, STANDPIPE OR THERMISTOR INSTALLATION	
		DESCRIPTION	STRATA PLOT	ELEV. DEPTH (m)	NUMBER	TYPE	BLOWS/0.3m	CORE No. CORE RECOVERY %	NUMBER		SCN	ANALYSED	WATER CONTENT % Wp — W — WI 10 20 30 40				
0	Track Mounted Rotary Drill Air Rotary (Casing: 152 mm.)	Ground Surface		0.00													Concrete
1		FILL - (SP/GP) SAND & GRAVEL, brown, no odours, no staining, inferred sub-rounded to sub-angular cobbles; non-cohesive, moist, compact.															
2																	Sand SV 1" PVC Screen
3																	Bentonite
3		- wet to saturated at 3m															
3.66		End of Borehole.		3.66													12/8/2015 Sand MW 2" PVC Screen
4																	
5																	
6																	
7																	
8																	
9																	
10																	

National IM Server: GINT\_GAL\_NATIONAL\IM Unique Project ID: Output Form BC\_BOREHOLE (GEOENVIRO)\_KTAaaka 24/2/16

DEPTH SCALE  
1 : 50



SOIL CLASSIFICATION SYSTEM: GACS

LOGGED: [REDACTED]  
CHECKED: [REDACTED]