



**SNC-LAVALIN**  
**Environment**

Client :  
Government of Yukon

**Borehole No. : 09-4**

Location :  
Land Treatment Facility, Dawson City, Yukon Territory


(Page 1 of 1)

Drilling Contractor: Geotech Drilling Services Ltd.  
Drilling Method : Odex

Project Number :   
Borehole Logged By :   
Date Drilled : 2009 09 19  
Log Typed By :

Pipe/Slotted Pipe Dia. (m): 0.05, 0.05

Depth in Metres	Drilling Legend	Water/NAPL Levels	Stratigraphy Plot	Sample Interval/ Core Run	Sample Number	Blow Count	% Recovery	Soil Vapour (ppm)	Well Name: MW09-4
	Sample Interval Odex	Water Level 1 Water Level 2 NAPL NAPL							
Soil Description									
0	BEDROCK, weathered, rock fragments, ultramafic rock, some sand, brown, fractured, pulverized, moist.								
1	ULTRAMAFIC ROCK, some coarse grained sand size fragments, quartz, serpentine, igneous parentage, massive, competent, pulverized rock flour, dry.				4-01				
2									
3									
4					4-02				
5									
6					4-03				
7									
8	End of borehole at 7.5 m.								
9									
10									



**Notes:**  
 Bolded sample denotes sample analyzed.  
 Composite samples collected of disturbed pulverized rock.