

WHITEHORSE SEWAGE TREATMENT FACILITY			CLIENT: STANLEY ASSOCIATES ENGINEERING			TEST PIT NO: 11482-TP26																																		
PRIMARY TREATMENT LAGOONS			EXCAVATOR: CAT 225			PROJECT NO: [REDACTED]																																		
WHITEHORSE, YUKON			UTM ZONE: 8 N6740897.4 E495189.9			ELEVATION: 690.90 (m)																																		
SAMPLE TYPE			<input checked="" type="checkbox"/> GRAB			<input checked="" type="checkbox"/> NO RECOVERY																																		
DEPTH(m)			SAMPLE TYPE			SAMPLE NO			USC			SOIL SYMBOL			SOIL DESCRIPTION			<input checked="" type="checkbox"/> STANDARD PENETRATION <input type="checkbox"/>				<input checked="" type="checkbox"/> PERCENT GRAVEL <input type="checkbox"/>				<input type="checkbox"/> PERCENT SAND <input type="checkbox"/>				<input type="checkbox"/> PERCENT SILT OR FINES <input type="checkbox"/>				<input type="checkbox"/> PERCENT CLAY <input type="checkbox"/>				DEPTH(ft)		
																		10 20 30 40				20 40 60 80				20 40 60 80				20 40 60 80										
																		PLASTIC M.C. LIQUID																						
0.0															SAND AND GRAVEL - roots, silt and snow											0.0														
			1												GRAVEL - some sand, trace to some silt; matrix supported; coarse gravel rounded to sub rounded; smooth; cobbles to 250 mm; fine to medium sand; frozen; brown - root fibres to 0.7 m - sand and silt - some gravel inclusions @ 0.3 to 0.7 m - becomes grey and sandy below 0.9 m											2.0														
			2																							4.0														
			3																							6.0														
			4																							8.0														
			5																							10.0														
																										12.0														
																										14.0														
																										16.0														
																										18.0														
																										20.0														
																										22.0														
6.0																		END OF TESTPIT @ 5.6 m - no sloughing - no ground water																						
7.0																																								

EBA Engineering Consultants Ltd.
Whitehorse, Yukon

LOGGED BY: [REDACTED]
REVIEWED BY: [REDACTED]
Fig. No:

COMPLETION DEPTH: **
COMPLETE: 95/01/09