



GEOLOGIC LOG OF DRILL HOLE NO.: TH05-11

DEPTH (m)	SYMBOL	SAMPLE No.	LITHOLOGY	PIEZOMETER DETAILS	HYDRAULIC CONDUCTIVITY CM/SEC			DISCONTINUITY DATA	ROCK STRENGTH BASED ON POINT LOAD TEST (MPa) (a)=axial; (d)=diametrical	TEMPERATURE	FIELD/LAB DATA							
					10-6	10-4	10-2	SEE BOTTOM OF FORM FOR CODES			SPT/LPT N	WATER CONTENT %		R.Q.D. %				
			(continued from previous page)					Dip Angle 30 60										
21																		
22																		
23																		
24																		
25																		
26																		
27																		
28																		
29																		
30																		
31																		
32																		
33																		
34																		
35																		
36																		
37																		
38																		
39																		
40			39.6 1,272.9 BEDROCK.															
41			- Between 39.6 m and 42.7 m depth: upper one-third is subangular pebbles to cobbles, lower two-third is foliated rhyolite overlying tuffaceous argillite.															
42																		
43				Piezometer 11A														
44																		
45																		

KC ROCK-SIG4 WOLVERINE TEST HOLES - NOV 17.GPJ ROCK-LOG.GDT 2/8/06

DISCONTINUITY CODES: B: BEDDING D: DRILL BRK F: FAULT G: GNEISS'TY J: JOINT M: SCHIST'TY S: SHEAR T: TENSION CRK
 CORE LOSS FRACTURED/BROKEN CORE DIP ANGLES MEASURED WITH RESPECT TO



GEOLOGIC LOG OF DRILL HOLE NO.: TH05-11

DEPTH (m)	SYMBOL	SAMPLE No.	LITHOLOGY	PIEZOMETER DETAILS	HYDRAULIC CONDUCTIVITY CM/SEC			DISCONTINUITY DATA	ROCK STRENGTH BASED ON POINT LOAD TEST (MPa) (a)=axial; (d)=diametrical	TEMPERATURE	FIELD/LAB DATA									
					10-6	10-4	10-2				SEE BOTTOM OF FORM FOR CODES	Dip Angle 30 60	SPT/LPT N ● CORE RECOVERY %			WATER CONTENT % ○ R.Q.D. %				
			(continued from previous page)																	
46			46.3 1,266.2 End of Hole at: 46.3 m																	
47																				
48			Notes:																	
49			1. No SPT or LPT testing was carried out in TH05-11 due to abundance of cobbles and boulders.																	
50			2. Two separate holes were drilled for the overburden and bedrock piezometers to facilitate installation and increased reliability of piezometric data.																	
51			3. Piezometer stickup lengths are as follows:																	
52			- TH05-11A = 0.40 m;																	
53			- TH05-11B = 0.39 m.																	
54			4. Water levels measured in piezometers TH05-11A and B after installation were 9.37 m and 8.50 m, respectively.																	
55																				
56																				
57																				
58																				
59																				
60																				
61																				
62																				
63																				
64																				
65																				
66																				
67																				
68																				
69																				
70																				

KC ROCK-SIG: WOLVERINE TEST HOLES - NOV 17.GPJ ROCK-LOG.GDT 2/8/05

DISCONTINUITY CODES: B: BEDDING D: DRILL BRK F: FAULT G: GNEISS'TY J: JOINT M: SCHIST'TY S: SHEAR T: TENSION CRK
 CORE LOSS FRACTURED/BROKEN CORE DIP ANGLES MEASURED WITH RESPECT TO