

Depth (m)	Method	Soil Description	Ground Ice Description	Sample Type	Sample Number	Moisture Content (%)	Plastic Limit	Moisture Content	Liquid Limit	Depth (ft)	
0							20	40	60	80	0
0 - 4.1	Solid stem auger	SAND (FILL) - silty, trace gravel, poorly graded, frozen, loose, light brown, organic inclusions, - dry - trace cobbles, inclusions of glass and metal garbage - possible weathered and fractured bedrock, no visible inclusions	Seasonally Frozen Unfrozen		SA07 SA08 SA09 SA10	6.8 12.3 5.1 1.9				0 1 2 3 4 5 6 7 8 9 10 11 12 13	
4.1 - 10		END of BOREHOLE at 4.1 m (Auger Refusal).								14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32	



Contractor: Donjeck Drilling

Completion Depth: 4 m

Drilling Rig Type: Truck Mounted CME75

Start Date: 2016 November 3

Logged By: [REDACTED]

Completion Date: 2016 November 3

Reviewed By:

Page 1 of 1