

MONITORING WELL LOG

MW22

SUPERVISOR: [REDACTED]
 TYPE OF RIG: **Hollow Stem Auger**
 CONTRACTOR: [REDACTED]
 DATE DRILLED: **May 24, 2003**
 GROUND ELEV.: **633.24**

NORTHING: 6733846
 EASTING: 496147
 ELEV. TOP OF PVC: **633.240** M-ASL
 DEPTH TO WATER: **2.91** M-BTOC
 ELEV. OF WATER: **630.33** M-ASL

| Depth (m) | Elev. (m-asi) | LITHOLOGY | SAMPLES NAMES AND DEPTHS | WELL DIAGRAM | VapourS (ppm) |
|---|---------------|--|--------------------------|---|--|
| 0.0 | 633.2 | Ground surface | | | |
| 1.0 | 632.2 | Sand and gravel with intermittent wood debris and organic material | | | NA |
| 2.0 | 631.2 | light brown sand and gravel, moist, loose, slight hydrocarbon odour, sweet odour | | | 25 |
| 3.0 | 630.2 | same as previous, increased moisture, slight hydrocarbon odour with depth | | | 50 |
| 4.0 | 629.2 | light brown to dark brown sand and gravel, wet, loose | | | 25 |
| 5.0 | 628.2 | dark brown, gravel, saturated, loose | | | 50 |
| 6.0 | 627.2 | dark brown gravel, saturated, loose | | | 25 |
| 7.0 | 626.2 | dark brown gravel, saturated, loose | | | 25 |
| 8.0 | 625.2 | | | | 25 |
| 9.0 | 624.2 | End of hole at 30 feet | | | 25 |
| | | Bentonite Sandpack Cuttings/Sand Backfill/Slough | | Top Of Screen Bottom Of Screen Top Of Sandpack Bottom Of Sandpack Top Of Bentonite Bottom Of Bentonite | 3.0 6.1 2.7 6.1 2.1 2.7 |
| | | ▼ Water Level: Date: June, 2003 | | | |
| SITE INVESTIGATION 146 Industrial Rd, Whitehorse, Yukon Territory PGL File: [REDACTED] | | | [REDACTED] | | |