

Proposed Waste Water Disposal Facility		CLIENT: [REDACTED]	PROJECT NO. - TESTPIT NO.						
Lagoon Site		EXCAVATOR: Linkbelt 210C	[REDACTED] TP14-03						
Ross River, YT		6874550N; 632618E; Zone 8	ELEVATION: 696.4 m						
SAMPLE TYPE <input type="checkbox"/> DISTURBED <input type="checkbox"/> NO RECOVERY <input type="checkbox"/> SPT <input type="checkbox"/> A-CASING <input type="checkbox"/> SHELBY TUBE <input type="checkbox"/> CORE BACKFILL TYPE <input type="checkbox"/> BENTONITE <input type="checkbox"/> PEA GRAVEL <input type="checkbox"/> SLOUGH <input type="checkbox"/> GROUT <input type="checkbox"/> DRILL CUTTINGS <input type="checkbox"/> SAND									
Depth (m)	SOIL DESCRIPTION	SAMPLE TYPE	SAMPLE NUMBER	GROUND ICE DESCRIPTION AND COMMENTS	<input type="checkbox"/> BULK DENSITY (kg/m ³) <input type="checkbox"/> 1400 1600 1800 2000		<input checked="" type="checkbox"/> CLAY (%) <input checked="" type="checkbox"/> 20 40 60 80		Elevation (m)
					<input checked="" type="checkbox"/> SPT (N) <input checked="" type="checkbox"/> 20 40 60 80		<input checked="" type="checkbox"/> SILT (%) <input checked="" type="checkbox"/> 20 40 60 80		
					PLASTIC M.C. LIQUID <input type="checkbox"/> 20 40 60 80		<input checked="" type="checkbox"/> SAND (%) <input checked="" type="checkbox"/> 20 40 60 80		
0	ORGANICS - grass, rootlets, soil seasonally frozen, dark brown. SILT - trace sand, firm, moist, brown.		G1	FROZEN UNFROZEN					696.0
1	GRAVEL - sandy, trace silt, compact subrounded particles, well graded, damp to moist, grey, trace to some cobbles, trace boulders.		G2						695.0
2			G3						694.0
3	- saturated, water table		G4						693.0
4	SILT - some clay, trace sand, firm, moist to wet, grey. END of TESTPIT @ 4.2 m.		G5						692.0
5									
[REDACTED]				LOGGED BY: [REDACTED]	COMPLETION DEPTH: 4.2m				
[REDACTED]				REVIEWED BY: [REDACTED]	COMPLETE: 14/10/24				
[REDACTED]				DRAWING NO:	Page 1 of 1				