


CLIENT: [REDACTED]	PROJECT: Clinton Creek Remediation Project	TEST PIT NO: TP18-08
CONTRACT: [REDACTED]	Clinton Creek, Yukon	PROJECT NO: [REDACTED]
EXCAVATION METHOD: Hand Dug Test Pit in Cut Bank	NORTHING: 7147492.78 EASTING: 513073.57	ELEVATION: 442.3 m
SAMPLE TYPE	<input checked="" type="checkbox"/> TUBE	<input type="checkbox"/> NO RECOVERY
	<input checked="" type="checkbox"/> SPLIT SPOON	<input type="checkbox"/> GRAB
	<input type="checkbox"/> MUD RETURN	<input type="checkbox"/> CORE RETURN



BOREHOLE LOG CLINTONCREEK.GPJ 1/17/19

[REDACTED]	LOGGED BY: [REDACTED]	COMPLETION DEPTH: 1.6 m
[REDACTED]	ENTERED BY: [REDACTED]	COMPLETION DATE: 9/8/2018
		Page 1 of 1