BELLE	EVIEW SUBDIVISION	CLIENT:					BOREHOLE NO: 4561-04			
LOT #33		DRILL: JOHN DEERE 410 BACKHOE					PROJECT:			
WATSON LAKE, YUKON										
SAMPLE TYPE DISTURBED NO RECOVERY SPT			A-CASING							
BACKFILL TYPE BENTONITE PEA GRAVEL III SLOUGH			GROUT							
	E SOIL DESCRIPTION			SAMPLE NUMBER	GROUND ICE DESCRIPTION	BULK DEI 1400 160	NSITY (kg/m ³)	◆ CLAY (%) ◆ 20 40 60 80		
E				IUM		S	PT (N) ■ 0 60 80	● SILT (%) ● 20 40 60 80	Depth (ft)	
spth	DESCRIPTION			∠ Щ	AND			▲ SAND (%) ▲	epth	
ð				MPI	COMMENTS		I.C. LIQUID	20 40 60 80 ■ GRAVEL (%) ■	Δ	
			SAMPLI	SA		20 40	60 80	20 40 60 80	0	
- 0	PEAT MOSS(PT)-root mat, and organic silt GRAVEL AND SAND(GP)-clean, with		-						0	
-	occasional cobble 200 mm;								-	
[subrounded to subangular, smooth gravel; coarse to fine grained sand; interbedded with thinly								-	
-	sand; interbedded with thinly bedded lenses of medium to fine								-	
	grained sand; damp to moist;									
-	compact(est.); brownish grey								-	
- 1									_	
_ '										
-									-	
-			-						-	
				Т.,					5	
-									-	
-									-	
_ 2									-	
-										
	-100 mm lens of iron oxide stained gravel									
-	giavei			2		•			_	
				1					▼ -	
-									-	
3							· · · · · · · · · · · · · · · · · · ·		40 -	
-									10	
-									-	
—									-	
-	END OF TEST PIT 3.4 m								_	
									-	
-	NOTE: 25 mm PVC standpipe installed to 3.3 m								-	
_ 4							• • • • • • • • • • • • • • • • • • • •		-	
┝									-	
L I										
$\mid \mid$									15	
									-	
F										
5								LETION DEPTH: 3.4	16 <u>-</u> m	
			RE	LOGGED BY: REVIEWED BY:			COMPLETE: 1986-08-11			
					NG NO: 4561-	4	Page 1 of 1			

WHITEHORSE ZONE9.GPJ EBA.GDT 21-10-5