

BELLEVIEW SUBDIVISION	CLIENT: ██████████	BOREHOLE NO: 4561-07
LOT #29	DRILL: JOHN DEERE 410 BACKHOE	PROJECT: ██████████
WATSON LAKE, YUKON		

SAMPLE TYPE	<input type="checkbox"/> DISTURBED	<input type="checkbox"/> NO RECOVERY	<input type="checkbox"/> SPT	<input type="checkbox"/> A-CASING	<input type="checkbox"/> SHELBY TUBE	<input type="checkbox"/> CORE
BACKFILL TYPE	<input type="checkbox"/> BENTONITE	<input type="checkbox"/> PEA GRAVEL	<input type="checkbox"/> SLOUGH	<input type="checkbox"/> GROUT	<input type="checkbox"/> DRILL CUTTINGS	<input type="checkbox"/> SAND

Depth (m)	SOIL DESCRIPTION	SAMPLE TYPE	SAMPLE NUMBER	GROUND ICE DESCRIPTION AND COMMENTS	BULK DENSITY (kg/m ³)		CLAY (%)		SILT (%)		SAND (%)		Depth (ft)
					1400	1600	1800	2000	20	40	60	80	
0	PEAT MOSS(PT)-root mat, and organic silt												0
0	GRAVEL AND SAND(GP)-clean, with occasional cobble 150 mm; subrounded to subangular, smooth gravel; interbedded with thinly bedded lenses of medium to fine grained sand; damp; compact(est.); brownish grey		1										0
1													1
2			2										2
3	SAND(SP)-trace gravel, trace silt; interbedded lens of fine grained, uniform, homogenous; damp; compact(est.)												3
3	GRAVEL AND SAND(GP)-clean												3
4	END OF TEST PIT 3.8 m												4
4	NOTE: 25 mm PVC standpipe installed to 3.7 m												4
5													5

██████████	LOGGED BY: ██████████	COMPLETION DEPTH: 3.8m
	REVIEWED BY: ██████████	COMPLETE: 1986-08-11
	DRAWING NO: 4561-7	Page 1 of 1