

BELLEVIEW SUBDIVISION	CLIENT: [REDACTED]	BOREHOLE NO: 4561-09
LOT #15	DRILL: JOHN DEERE 410 BACKHOE	PROJECT: [REDACTED]
WATSON LAKE, YUKON		

SAMPLE TYPE	<input type="checkbox"/> DISTURBED	<input type="checkbox"/> NO RECOVERY	<input type="checkbox"/> SPT	<input type="checkbox"/> A-CASING	<input type="checkbox"/> SHELBY TUBE	<input type="checkbox"/> CORE
BACKFILL TYPE	<input type="checkbox"/> BENTONITE	<input type="checkbox"/> PEA GRAVEL	<input type="checkbox"/> SLOUGH	<input type="checkbox"/> GROUT	<input type="checkbox"/> DRILL CUTTINGS	<input type="checkbox"/> SAND

Depth (m)	SOIL DESCRIPTION	SAMPLE TYPE	SAMPLE NUMBER	GROUND ICE DESCRIPTION AND COMMENTS	BULK DENSITY (kg/m <sup>3</sup> )		CLAY (%)		SILT (%)		SAND (%)		Depth (ft)
					1400	1600	1800	2000	20	40	60	80	
0	PEAT MOSS(PT)-root mat, and organic silt												0
1	GRAVEL(GP)-sandy, clean, with occasional cobble; subrounded to subangular, smooth gravel; coarse to medium grained sand; interbedded with medium bedded lenses of fine grained, uniform sand, trace gravel, lenses 200 mm thick; damp; compact(est.); brownish grey		1										5
2			2										10
3													15
4													15
5	END OF TEST PIT 4.1 m NOTE: 25 mm PVC standpipe installed to 4.0 m												16

[REDACTED]	LOGGED BY: [REDACTED]	COMPLETION DEPTH: 4.1m
[REDACTED]	REVIEWED BY:	COMPLETE: 1986-08-11
[REDACTED]	DRAWING NO: 4561-9	Page 1 of 1