

BELLEVIEW SUBDIVISION	CLIENT: ██████████	BOREHOLE NO: 4561-10
LOT #11	DRILL: JOHN DEERE 410 BACKHOE	PROJECT: ██████████
WATSON LAKE, YUKON		

SAMPLE TYPE	<input checked="" type="checkbox"/> DISTURBED	<input type="checkbox"/> NO RECOVERY	<input type="checkbox"/> SPT	<input type="checkbox"/> A-CASING	<input type="checkbox"/> SHELBY TUBE	<input type="checkbox"/> CORE
BACKFILL TYPE	<input checked="" type="checkbox"/> BENTONITE	<input type="checkbox"/> PEA GRAVEL	<input type="checkbox"/> SLOUGH	<input type="checkbox"/> GROUT	<input type="checkbox"/> DRILL CUTTINGS	<input type="checkbox"/> SAND

Depth (m)	SOIL DESCRIPTION	SAMPLE TYPE	SAMPLE NUMBER	GROUND ICE DESCRIPTION AND COMMENTS	BULK DENSITY (kg/m³)		CLAY (%)		SILT (%)		SAND (%)		Depth (ft)
					1400	1600	1800	2000	20	40	60	80	
0	PEAT MOSS(PT)-root mat, and organic silt												0
0	GRAVEL AND SAND(GP)-clean, with occasional cobble 150 mm; subrounded to subangular, smooth gravel; coarse to medium grained sand; interbedded with thinly bedded lenses of fine grained uniform sand, lenses 100 mm thick; damp; compact(est.); greyish brown		1										0
1													1
2	-30 mm lens of iron oxide stained and black gravel, trace organics		2										2
3													3
4	END OF TEST PIT 3.3 m NOTE: 25 mm PVC standpipe installed to 3.1 m												4
5													5

Archive

██████████	LOGGED BY: ██████████	COMPLETION DEPTH: 3.3m
	REVIEWED BY: ██████████	COMPLETE: 1986-08-11
	DRAWING NO: 4561-10	Page 1 of 1