

BELLEVIEW SUBDIVISION	CLIENT: GOVERNMENT OF YUKON	BOREHOLE NO: 4561-15
LOT #9	DRILL: JOHN DEERE 410 BACKHOE	PROJECT: [REDACTED]
WATSON LAKE, YUKON		

SAMPLE TYPE	<input type="checkbox"/> DISTURBED	<input type="checkbox"/> NO RECOVERY	<input type="checkbox"/> SPT	<input type="checkbox"/> A-CASING	<input type="checkbox"/> SHELBY TUBE	<input type="checkbox"/> CORE
BACKFILL TYPE	<input type="checkbox"/> BENTONITE	<input type="checkbox"/> PEA GRAVEL	<input type="checkbox"/> SLOUGH	<input type="checkbox"/> GROUT	<input type="checkbox"/> DRILL CUTTINGS	<input type="checkbox"/> SAND

Depth (m)	SOIL DESCRIPTION	SAMPLE TYPE	SAMPLE NUMBER	GROUND ICE DESCRIPTION AND COMMENTS	BULK DENSITY (kg/m ³)		CLAY (%)		SILT (%)		SAND (%)		Depth (ft)
					1400	1600	1800	2000	20	40	60	80	
0	PEAT MOSS(PT)-root mat, and organic silt												0
	SAND(SP/SM)-trace to some silt, medium to fine grained, uniform												
1	GRAVEL AND SAND(GP)-clean, with occasional cobble 150 mm; subrounded to subangular, smooth gravel; coarse to medium grained sand; interbedded with medium bedded lenses of medium to fine grained sand lenses 200 mm thick, wavy, parallel, continuous; damp; compact(est.); greyish brown												5
2			1										10
3													15
4	END OF TEST PIT 3.8 m NOTE: 25 mm PVC standpipe installed to 3.5 m												16

Archive

[REDACTED]	LOGGED BY: [REDACTED]	COMPLETION DEPTH: 3.8m
	REVIEWED BY: [REDACTED]	COMPLETE: 1986-08-12
	DRAWING NO: 4561-15	Page 1 of 1