

BELLEVIEW SUBDIVISION	CLIENT: [REDACTED]	BOREHOLE NO: 4561-19
LOT #45	DRILL: JOHN DEERE 410 BACKHOE	PROJECT: [REDACTED]
WATSON LAKE, YUKON		

SAMPLE TYPE	<input type="checkbox"/> DISTURBED	<input type="checkbox"/> NO RECOVERY	<input type="checkbox"/> SPT	<input type="checkbox"/> A-CASING	<input type="checkbox"/> SHELBY TUBE	<input type="checkbox"/> CORE
BACKFILL TYPE	<input type="checkbox"/> BENTONITE	<input type="checkbox"/> PEA GRAVEL	<input type="checkbox"/> SLOUGH	<input type="checkbox"/> GROUT	<input type="checkbox"/> DRILL CUTTINGS	<input type="checkbox"/> SAND

Depth (m)	SOIL DESCRIPTION	SAMPLE TYPE	SAMPLE NUMBER	GROUND ICE DESCRIPTION AND COMMENTS	BULK DENSITY (kg/m <sup>3</sup> )		CLAY (%)		SILT (%)		SAND (%)		Depth (ft)
					1400	1600	1800	2000	20	40	60	80	
0	PEAT MOSS(PT)-root mat, and organic silt												0
0	GRAVEL AND SAND(GP)-clean, with occasional cobble 200 mm; subrounded to subangular; smooth gravel; coarse to medium grained sand; interbedded with medium bedded lenses of fine grained, uniform sand, even, parallel, continuous; damp; compact(est.); greyish brown		1										0
1													1
2			2										2
3													3
4													4
4.1	END OF TEST PIT 4.1 m												4.1
	NOTE: 25 mm PVC standpipe installed to 3.9 m												

Archive

[REDACTED]	LOGGED BY: [REDACTED]	COMPLETION DEPTH: 4.1m
[REDACTED]	REVIEWED BY:	COMPLETE: 1986-08-12
[REDACTED]	DRAWING NO: 4561-19	Page 1 of 1