

Borehole Log: 10MW06-9

Project No: [REDACTED]

Project: Whitehorse Airport

Client: PWGSC

Location: Whitehorse

Logged By: [REDACTED]

Checked By: [REDACTED]

SUBSURFACE PROFILE			SAMPLE		VOC Concentration		Well Completion Details
Depth	Symbol	Description	Depth/Elev.	Sample No.	Type	ppm	
0		Ground Surface					
0		ASPHALT					
1		SAND Sand, trace silt, medium grained, dense, brown to grey, dry		9-1	G	0	
2							
3							
4		SAND Sand, dense, grey, wet		9-2	G	0	
5							
6							
7		SILT Silt, stiff, grey, dry		9-3	G	10	
8							
9							
10		SILT Silty clay, stiff, grey, moist to wet		9-4	G	0	
11							
12							
13		SAND Sand, dense, grey, wet		9-5	G	5	
14							
15							
16		SILT Silty clay, stiff, grey, moist to wet		9-6	G	0	
17							
18							
19		SILT Silty clay, stiff, grey, moist to wet		9-7	G	10	
20							
21							
22		SAND Sand, dense, grey, wet		9-8	G	0	
23							
24							
		End of Borehole					

Drilled By: [REDACTED]

Hole Dia: 10 cm

Well Dia: 55mm

Drill Method: Geoprobe

Grnd Elev: NA

TOC Elev: NA

Drill Date: 06/07/10

Sheet: 1 of 1