FINAL

[redacted]

Client
Yukon Government

Borehole No. : 22-BH-02-S

Location
Wellgreen Mill, YT

PAGE 1 OF 1

Drilling Contractor [redacted]
Drilling Method Vibratory Sonic
Borehole Dia. (m) 0.05
Pipe/Slotted Pipe Dia. (m) none/none

Date Monitored n/a
Ground Surface Elev. (m) 790.900
Top of Casing Elev. (m) n/a
Northing: 6820282.903 Easting: 589379.395

Project Number: [redacted]
Borehole Logged By:
Date Drilled: 2022 09 12
Log Typed By:

Drilling Legend
Sample Interval
Vibrasonic

Water/ Levels
Water Level 1
Water Level 2

Reading within indicated scale
Reading outside indicated scale

Soil Vapour (ppm)
10^1 10^2 10^3 10^4

Depth in Metres	Soil Description	Stratigraphy Plot	Sample Interval Core Run	Sample Number	Blow Count	% Recovery
0	SAND (TAILINGS), fine grained, hardpan chunks, orange, red mottling, oxide, moist to wet.					
1						
	UNOXIDIZED TAILINGS, sandy, fine grained, trace silt, grey, loose, wet.					
2						
3						
	SILT, sandy, trace clay, brown to grey, firm, moist.			02S-04		
4	SAND, coarse grained, some silt, grey, loose, moist.					
	CLAY, silty, trace fine gravel, grey, soft, damp.					
5	Below 4.5 m - more subrounded gravel.					
6						
	Bottom of hole at 6.4 m.					
7						
8						
9						
10						

BENTONITE/CUTTINGS
PELTONITE
SAND

NOTES
Bold sample denotes sample analyzed.